

HRM1001 Mens Full Zip Sweat Jacket

POINT	MEASUREMENT POINT	SIZE									
		S	M	L	XL	2XL	3XL	4XL	5XL	6XL	
A	TOTAL LENGTH FRM HPS (CM)	71	72.5	74	75.5	77	78,5	80	81.5	83	
B	HALF CHEST (CM)	55	57	59	62	65	69	73	77	81	
J	SLEEVE LENGTH (CM)	63	64	65	66	67	68	69	70	71	

Maßtoleranz bei ½ Oberweite +/- 1,5 cm und bei Länge +/- 2,0 cm - Dimensional tolerance for ½ chest +/- 1.5 cm and length +/- 2.0 cm

