

## CEL005 - EXPERT ACTIVE SOFTSHELL JACKET

MEASURING POINTS IN INCHES		XS	S	M	L	XL	XXL	3XL	TOLERANCE
GARMENT MEASUREMENTS									
A	FULL CHEST CIRCUMFERENCE (2" below armhole)	40	42	44	47	50	53	56	0,5
D	CB LENGTH	28	29	30	30	31	31	31,5	0,5
H	SLEEVE LENGTH (from neck point to end of cuff)	31	31,5	32	32,5	33	33,5	34	0,25